

# Lab Comments -- 4th Quarter 1999

4th Quarter 1999

Page 1 of 9

## ACKLEY

WELL 3

Lab No.: 199908982 MtBE = 0.6 ug/L, tc 10/21/99.

## ALBION

WELL 1

Lab No.: 199908931 Stand by well didn't want to start up just for a sample.

Lab No.: 199908931 no sample Cancel 10-18-99 SH

## ALGONA

WELL 6

Lab No.: 199908659 will resample.

WELL 7

Lab No.: 199908660 will resample.

Lab No.: 199909014 time on the label 07:55.

## ANAMOSA STATE PARK

WELL 1

Lab No.: 199910608 Well 1 closed for the season 10-15 thru 4-1.

Lab No.: 199910608 no sample Canceled 12-1-99 SH

## APLINGTON

WELL 2

Lab No.: 199909431 Cancelled one BEDDIEMS test because logged off using wrong report

Lab No.: 199909431 format. sm 11/01/99

Lab No.: 199909431 Cancelled one BEDDIESW test because wrong report format. sm 11/04/99

## ASBURY SUN VALLEY

WELL 2

Lab No.: 199909016 Sun Valley

## ATKINS

WELL 1

Lab No.: 199908989 as Mike Jennings;per the label 13:15 and Nelson.

WELL 2

Lab No.: 199908990 as Mike Jennings;per the label 13:00 and Nelson.

## ATLANTIC

WELL 9

Lab No.: 199908980 No sample Cancel 10-19-99 SH

Lab No.: 199908980 Well Rehab.

## BETTENDORF-DODDS VALLEY VIEW

WELL 1

Lab No.: 199909472 Dodds Valley View Water Assoc.

## BRIGHTON

WELL 1

Lab No.: 199909266 Well 1 has been capped off & sealed at ground level.

---

Lab No.: 199909266 no sample Canceled 10-20-99 SH

WELL 2

Lab No.: 199909264 P.O. #101899

## CEDAR FALLS

WELL 6

Lab No.: 199909497 Canceled BEDDIESW test due to possible contamination. Request that

Lab No.: 199909497 client recollect. sm 11/21/99

Lab No.: 199909497 Replacement for this sample is #9910853.

Lab No.: 199910853 The sample is a replacement for sample #9909497.

## CEDAR RAPIDS

WELL E1

Lab No.: 199910054 no sample Canceled 11-12-99 SH

Lab No.: 199910054 Out of Service.

WELL E10

Lab No.: 199910062 Out of Service.

Lab No.: 199910062 no sample Canceled 11-12-99 SH

WELL E11

Lab No.: 199910061 no sample Canceled 11-12-99 SH

Lab No.: 199910061 Out of Service.

WELL E14

Lab No.: 199909443 The liter samples erroneously lists W-14 on the label. The vials and

Lab No.: 199909443 paperwork lists Well E14.

WELL E2

Lab No.: 199910053 Out of Service.

Lab No.: 199910053 no sample Canceled 11-12-99 SH

WELL E3

Lab No.: 199910055 no sample Canceled 11-12-99 SH

Lab No.: 199910055 Out of Service.

WELL E4

Lab No.: 199910056 Out of Service.

Lab No.: 199910056 no sample Canceled 11-12-99 SH

WELL E5

Lab No.: 199910057 no sample Canceled 11-12-99 SH

Lab No.: 199910057 Out of Service.

WELL E8

Lab No.: 199910063 Out of Service.

Lab No.: 199910063 no sample Canceled 11-12-99 SH

WELL SEM2

Lab No.: 199909437 Canceled BEDDIESW test due to possible in-house contamination.

Lab No.: 199909437 Requested that client resample. sm 11/05/99

Lab No.: 199909437 Replacement sample #9910064 11-12-99 KLP

WELL SEM3

Lab No.: 199910051 Out of Service.

Lab No.: 199910051 no sample Canceled 11-12-99 SH

WELL SEM5

Lab No.: 199910052 Out of Service.

Lab No.: 199910052 no sample Canceled 11-12-99 SH

---

WELL W3

Lab No.: 199910060 Out of Service.  
Lab No.: 199910060 no sample Canceled 11-12-99 SH

WELL W5

Lab No.: 199910059 Out of Service.  
Lab No.: 199910059 no sample Canceled 11-12-99 SH

WELL W8

Lab No.: 199910058 Out of Service.  
Lab No.: 199910058 no sample Canceled 11-12-99 SH

## CHARLES CITY

WELL 4

Lab No.: 199909328 PO 705

## CLINTON IAWC

WELL 10

Lab No.: 199910648 Cancelled one BEDDIESW test due to matrix spike report format was  
Lab No.: 199910648 used incorrectly for sample. sm 12/14/99

WELL 11

Lab No.: 199910649 Cancelled one BEDDIESW test as the matrix spike report format was  
Lab No.: 199910649 used incorrectly for the sample result. sm 12/14/99

WELL 9

Lab No.: 199910647 Cancelled one BEDDIESW test due to matrix spike was completed in the  
Lab No.: 199910647 wrong test. sm 12/14/99

## DECORAH FREEPORT

WELL 1

Lab No.: 199909474 Freeport Water District

## DEWITT

WELL 3

Lab No.: 199909509 Cancelled BEDDIEMS that had incorrect report format. sm 11/04/99

## DONNELLSON

WELL 4

Lab No.: 199907799 Well #4 was plugged in 1970.  
Lab No.: 199907799 no sample Canceled 9-14-99 SH  
Lab No.: 199909644 Well is plugged.  
Lab No.: 199909644 no sample Canceled 11-1-99 SH

WELL 5

Lab No.: 199907800 no sample Canceled 9-14-99 SH  
Lab No.: 199907800 Well #5 was capped in 1979, no pump.  
Lab No.: 199909645 no sample Canceled 11-1-99 SH  
Lab No.: 199909645 Well is capped.

## DOWS

WELL 4

Lab No.: 199909633 Cancelled BEDDIESW test due to possible in-house contamination. Will  
Lab No.: 199909633 request resample. sm 11/17/99  
Lab No.: 199909633 Replacement sample is #9910561. 12-02-99 KLP  
Lab No.: 199910561 This sample is a replacement for sample #9909633.

---

## EDDYVILLE

### WELL 1

- Lab No.: 199909596 no sample Canceled 10-29-99 SH
- Lab No.: 199909596 Well #1 is no longer in use except for emergency use only.
- Lab No.: 199909596 Well #3 is the closest to an underground storage tank. I spoke to
- Lab No.: 199909596 Gale and she said this was fine. Richard Lewman

### WELL 3

- Lab No.: 199909594 Client sampled from well 3 instead of well 1.

## ELKADER

### WELL 5

- Lab No.: 199910025 no sample Cancel 11-10-99 SH
- Lab No.: 199910025 Well #5 is out of sample.

## FARMINGTON

### WELL 1

- Lab No.: 199909565 PO#102799

### WELL 2

- Lab No.: 199909566 PO #102799

## FORT DODGE

### WELL 14

- Lab No.: 199909758 Received liter bottle broken.
- Lab No.: 199909758 containers. SH 11-3-99
- Lab No.: 199909758 Replacement Sample #9909894 11-12-99 KLP
- Lab No.: 199909894 Resample for TEH original sample #9909758

### WELL 16

- Lab No.: 199909760 Received liter bottle broken.
- Lab No.: 199909760 containers. SH 11-3-99
- Lab No.: 199909760 Replacement sample #9909895 11-12-99 KLP
- Lab No.: 199909895 Resample for TEH original sample #9909760

### WELL 17

- Lab No.: 199909761 Received liter bottle broken.
- Lab No.: 199909761 containers. SH 11-3-99
- Lab No.: 199909761 Replacement sample #9909896 11-12-99 KLP
- Lab No.: 199909896 Resample for TEH original sample #9909761

## GARNAVILLO

### WELL 1

- Lab No.: 199909714 088

### WELL 2

- Lab No.: 199909715 088

## GARNER

### WELL 2

- Lab No.: 199909563 the liter bottle 09:30.

## GOODELL

### WELL 2

- Lab No.: 199909640 Cancelled BEDDIEMS as this sample doesn't have an MS/MSD. sm 11/02/99
-

## GRAFTON

### WELL 1

Lab No.: 199909560 on the liter bottle 07:10.

### WELL 2

Lab No.: 199909561 on the vials 07:12.

## GUTTENBERG

### WELL 1

Lab No.: 199911109 earliest time is 10:20.

## HAWKEYE

### WELL 3

Lab No.: 199909749 Client collected extra sample.

### WELL 4

Lab No.: 199909750 Client did not send in liter sample;per phone with D. Harris will

Lab No.: 199909750 send another container for Well 4. SH 11-3-99

Lab No.: 199909750 Replacement sample is #9909906. 11-12-99 KLP

Lab No.: 199909906 Resample for TEH, original sample #9909750.

## HUMBOLDT

### SPRING 1

Lab No.: 199909814 Will contact to resample.

### WELL 1

Lab No.: 199909813 Will contact to resample.

## INDEPENDENCE

### WELL 6

Lab No.: 199909735 Please note that MtBE was found at 0.49ug/l in the analysis of this

Lab No.: 199909735 sample.

### WELL 7

Lab No.: 199909736 Please note that MtBE was found at 0.85ug/l in the analysis of this

Lab No.: 199909736 sample.

## IOWA CITY

### WELL 1

Lab No.: 199911165 Wells are currently not running;per Tim Dingbaum.

Lab No.: 199911165 no sample Canceled 12-28-99 SH

## IOWA FALLS

### WELL ER3

Lab No.: 199909743 R Bend

### WELL PS1

Lab No.: 199909738 West

### WELL PS2

Lab No.: 199909739 North

### WELL PS3

Lab No.: 199909740 East

## JANESVILLE

### WELL 2

---

Lab No.: 199910242 Well 4 replaces Well 2 which has been out of service and sealed off.

Lab No.: 199910242 no sample Canceled 11-17-99 SH

WELL 4

Lab No.: 199910229 Well 4 replaces Well 2 which has been out of service and sealed off.

## KENSETT

WELL 2

Lab No.: 199910002 311 3rd st.

## LAKOTA

WELL 4

Lab No.: 199908083 Client sampled from well 4 instead of well 1.

## LECLAIRE

WELL 1

Lab No.: 199909816 Please note that MtBE was found at 1.4ug/L in the analysis of this

Lab No.: 199909816 sample.

## LIME SPRINGS

WELL 1

Lab No.: 199910015 time on the label 09:30.

## LOW MOOR

WELL 1

Lab No.: 199911108 Well #1 not available at this time.

Lab No.: 199911108 no sample Canceled 12-21-99 SH

## MANCHESTER

WELL 7

Lab No.: 199909991 Cancelled BEDDIESW test due to phthalate contamination. Client is to

Lab No.: 199909991 resample. sm 12/06/99

Lab No.: 199909991 Replacement sample for this is #9910854. tml 12/10/99

Lab No.: 199910854 This sample is a replacement for sample #9909991. tml 12/10/99

## MAQUOKETQA

WELL 3

Lab No.: 199910157 Please note that MtBE was observed at 1.6ug/l in the analysis of

Lab No.: 199910157 this sample.

WELL 4

Lab No.: 199910158 Please note that MtBE was observed at 1.3ug/l in the analysis

Lab No.: 199910158 of this sample.

## MARBLE ROCK

WELL 1

Lab No.: 199909994 No resample received for TEH, 1/4/00.

Lab No.: 199909994 BEDDIESW and BEDDIEMS tests cancelled due to suspected in-house

Lab No.: 199909994 contamination (numerous phthalates). Client is to recollect.

Lab No.: 199909994 sm 12/06/99

## MARION

WELL 5

Lab No.: 199909939 The replacement sample for this is #9910863. tml 12/10/99

---

- Lab No.: 199909939 Cancelled BEDDIESW test due to client needed to resample due to
- Lab No.: 199909939 suspected contamination. sm 12/22/99
- Lab No.: 199910863 This sample is a replacement for sample #9909939. tml 12/10/99

## MARQUETTE

### WELL 2

- Lab No.: 199909996 Replacement sample is #9910901.
- Lab No.: 199909996 earliest time is 11:25.
- Lab No.: 199909996 Cancelled BEDDIESW test because client recollected due to suspected
- Lab No.: 199909996 in-house contamination. sm 12/27/99
- Lab No.: 199910901 This sample is a replacement for sample #9909996.

## MASON CITY

### WELL 14

- Lab No.: 199910090 Well #14 - out of production due to re-casing well.
- Lab No.: 199910090 no sample Canceled 11-11-99 SH

### WELL 8

- Lab No.: 199910089 no sample Canceled 11-11-99 SH
- Lab No.: 199910089 Well #8 - out of production due to bad well pump.

## MEDIAPOLIS

### WELL 4

- Lab No.: 199910326 Well 4 is under construction right now and is not running.
- Lab No.: 199910326 no sample Canceled 11-17-99 SH

## MILES

### WELL 2

- Lab No.: 199910032 The liter bottle was broken in lab accident.

## MONTOUR

### WELL 1

- Lab No.: 199909922 Liter bottle received broken.

### WELL 2

- Lab No.: 199909923 MS & MSD
- Lab No.: 199909923 MtBE observed at 0.46 ug/L. tc,11/15/99.

## MORNING SUN

### WELL 1

- Lab No.: 199910287 The paperwork lists the collector as Wade Walker;per the label
- Lab No.: 199910287 Aaron Giese.

## MOUNT VERNON

### WELL 3

- Lab No.: 199911225 Labels on sampling containers not filled out.

## PERRY

### WELL 13

- Lab No.: 199910259 Received the liter sample broken. Will have client resample.
- Lab No.: 199910259 Replacement sample is #9910560. 12-02-99 KLP
- Lab No.: 199910560 This is a replacement sample for #9910259. tml 12/10/99

### WELL 18

---

Lab No.: 199910260 Received the liter sample broken. Will have client resample.  
Lab No.: 199910260 Replacement sample is #9910559. 12-02-99 KLP  
Lab No.: 199910559 This is a replacement sample for #9910260. tml 12/10/99

## PRINCETON

### WELL 1

Lab No.: 199910961 Old Well

### WELL 2

Lab No.: 199910962 New Well

## RIDGEWAY

### WELL 2

Lab No.: 199910266 time on the label 08:20.

## SHEFFIELD

### WELL 3

Lab No.: 199910406 Well #3 has no pump.  
Lab No.: 199910406 no sample Canceled 11-23-99 SH

## SPRINGVILLE

### WELL 1

Lab No.: 200000022 on the labels 10:21.

## UNION

### WELL 3

Lab No.: 199910684 Chlorine and bromine present in this sample reacted with the MS spike  
Lab No.: 199910684 compounds resulting in low recoveries. tc, 12/13/99.

## WALCOTT

### WELL 3

Lab No.: 199910809 earliest time is 10:07.

## WAUKON

### WELL 2

Lab No.: 199910635 no sample Canceled 12-1-99 SH  
Lab No.: 199910635 Well 2 we unable to sample motor is burned out. Will be fixed sometime  
Lab No.: 199910635 in December.

## WAYLAND

### WELL 1

Lab No.: 199910594 no sample Canceled 12-1-99 SH  
Lab No.: 199910594 Well 1 unable to collect sample down for repair.

## WEBSTER CITY

### WELL 6

Lab No.: 199910857 no sample Canceled 11-7-99 SH  
Lab No.: 199910857 Well 6 is out of service, will be on line possibly early next year.

## WEST BEND

### WELL 1

Lab No.: 199911214 WL01

### WELL 3

---



Lab No.: 199911215 WL03

WELL 5

Lab No.: 199911216 WL05

## WEST BURLINGTON

WELL 4

Lab No.: 199910947 Well #4 is inoperable at this time. Pump & Motor have been sent out

Lab No.: 199910947 no sample Canceled 12-13-99 SH

Lab No.: 199910947 for repair.

WELL 5

Lab No.: 199910948 no sample Canceled 12-13-99 SH

Lab No.: 199910948 Well #5 is inoperable at this time. We are waiting for contractor to

Lab No.: 199910948 replace a broken valve, well should be operable next month.

## WEST LIBERTY

WELL 2

Lab No.: 199910569 time on the label 10:05.

WELL 4

Lab No.: 199910571 time on the label 09:00.

## WINFIELD

WELL 1

Lab No.: 199910763 Client did not collect MS & MSD properly.

## WYOMING

WELL 2

Lab No.: 199910617 MTBE was observed at 6.13ug/l in the analysis of this sample.

---