

Iowa Department of Natural Resources
2011 Summary Information
Underground Storage Tanks (USTs)

General Information

Public Record Posted Date: 4/25/2012

Total Number Of UST Facilities: 2742

Total Number Of USTs: 7339

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 2236

Inspection Period Dates: 1/1/2011 To: 12/31/2011

Percent Compliance (Combined Measure): 87%

Summary Information For Releases

Number Of Confirmed UST Releases: 56

Release Reporting Period Dates: 1/1/2011 To: 12/31/2011

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during 2011. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	9	16							9	16						
Piping	11	20					2	4	4	7			5	9		
Dispenser																
STP																
Delivery Problem	3	5			3	5										
Other	33	59													33	59
Totals	56	100			3	5	2	4	13	23			5	9	33	59

= number, % = percent of total number of releases

Note: Release , source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural Resources. Source and cause data were collected from release reports submitted to the department.

Site specific information on UST compliance and releases can be obtained from our on-line database located at <https://programs.iowadnr.gov/ustlust/pages/advanced.aspx> or from the department's record center.