

Iowa Department of Natural Resources
2013 Summary Information
Underground Storage Tanks (USTs)

General Information

Public Record Posted Date: 10/16/2013

Total Number Of UST Facilities: 2,697

Total Number Of USTs: 7,714

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 1,615

Inspection Period Dates: 9/30/2012 To: 10/1/2013

Percent Compliance (Combined Measure): 78%

Summary Information For Releases

Number Of Confirmed UST Releases: 59

Release Reporting Period Dates: 9/30/2012 To: 10/1/2013

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2013. Some inspection reports had not been received when the chart was compiled. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	12	20	3	5					9	15						
Piping	21	36					2	3	19	32						
Dispenser																
STP																
Delivery Problem	6	10			6	10										
Other	20	34											2	3	18	32
Totals	59	100	3	5	6	10	2	3	28	47			2	3	18	32

= number, % = percent of total number of releases

Note: Release , source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural resources.

Source and cause data were collected from release reports submitted to the department.

Site specific information on UST compliance and releases can be obtained from our on-line database located at <https://programs.iowadnr.gov/ustlust/pages/advanced.aspx> or from the department's record center.