

# ASBESTOS-CONTAINING MATERIALS

In the past 3,600 products contained asbestos. Today, more than 3,000 products still contain asbestos. The following are representative examples of materials that contain asbestos that may be encountered during the renovation or demolition of a building.

If you suspect a material contains asbestos, have a licensed asbestos inspector sample it for analysis before disturbing the material!

# Vermiculite Wall Insulation



# Asphalt Roof Shingles



# Transite (Slate) Shingles



# Floor Tile — Both 9" x 9" and 12" x 12"



# Ceiling Tile



# Textured Ceiling



# Pipe Wrap

