

**Iowa Department of Natural Resources**  
**2017 Summary Information**  
**Underground Storage Tanks (USTs)**

**General Information**

Public Record Posted Date: 10/27/2017

Total Number Of Current UST Facilities: 2,546  
 Total Number Of Current USTs: 7,663

**0. Summary Information For On-Site Inspections**

Number Of UST Facilities Inspected: 1,943  
 Inspection Period Dates: 10/1/2016 To: 9/30/2017  
 Percent Compliance (Combined Measure): 61%

**Summary Information For Releases**

Number Of Confirmed UST Releases: 36  
 Release Reporting Period Dates: 10/1/2016 To: 9/30/2017

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2016. Some inspection reports are received after the chart is compiled. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
<b>Tank</b>	9	23							9	23%						
<b>Piping</b>	5	13					2	5%	3	8%						
<b>Dispenser</b>	13	33					6	15%					7	18%		
<b>STP</b>																
<b>Delivery Problem</b>	1	1			1	1%										
<b>Other</b>	12	25											6	15%	6	15%
<b>Totals</b>	40	100			1	1%	8	20%	12	31%			13	33%	6	15%

# = number, % = percent of total number of releases

Note: Release , source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural resources.

Source and cause data were collected from release reports submitted to the department. Site specific information on UST compliance and releases can be obtained from our on-line database located at <https://programs.iowadnr.gov/ustlust/pages/advanced.aspx> or from the department's record center.