

Iowa Department of Natural Resources

2019 Summary Information Underground Storage Tanks (USTs)

General Information

Public Record Posted Date: 10/1/2019

Total Number Of UST Facilities: 2506

Total Number Of USTs*: 7750

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 1255

Inspection Period Dates: 10/1/2018 To: 9/30/2019

Percent Compliance (Combined Measure): 56%

Summary Information For Releases

Number Of Confirmed UST Releases: 35

Release Reporting Period Dates: 10/1/2018 To: 9/30/2019

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2019. Some inspection reports had not been received when the chart was compiled. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

Source			Cause													
			Spill		Overfill		Phys/Mech		Corrosion		Install		Other		Unkown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank																
Piping																
Dispenser	7	20%					7	20%								
STP																
Delivery																
Other	28	80%					1	3%					5	14%	22	63%
Totals	35	100%					8	23%					5	14%	22	63%

= number, % = percent of total number of releases

Note: Release, source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural Resources.

* this is the count of tank compartments