

Iowa Department of Natural Resources

2020 Summary Information Underground Storage Tanks (USTs)

General Information

Public Record Posted Date: 10/30/2020

Total Number Of UST Facilities: 2492

Total Number Of UST Compartments: 7809

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 1127

Inspection Period Dates: 10/1/2019 To: 9/30/2020

Percent Compliance (Combined Measure): 64%

Summary Information For Releases

Number Of Confirmed UST Releases: 33

Release Reporting Period Dates: 10/1/2019 To: 9/30/2020

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2020. Some inspection reports had not been received when the chart was compiled. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

Source			Cause													
			Spill		Overfill		Phys/Mech		Corrosion		Install		Other		Unkown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	1	3%							1	3%						
Piping																
Dispenser	11	33%					11	33%								
STP																
Delivery																
Other	21	64%					4	12%					3	9%	14	42%
Totals	33	100%					15	46%	1	3%			3	9%	14	42%

= number, % = percent of total number of releases

Note: Release, source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural Resources.