

Iowa Department of Natural Resources

2021 Summary Information Underground Storage Tanks (USTs)

General Information

Public Record Posted Date: 10/1/2021

Total Number Of UST Facilities: 2482

Total Number Of UST Compartments: 7862

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 1269

Inspection Period Dates: 10/1/2020 To: 9/30/2021

Percent Compliance (Combined Measure): 66%

Summary Information For Releases

Number Of Confirmed UST Releases: 30

Release Reporting Period Dates: 10/1/2020 To: 9/30/2021

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2021. Some inspection reports had not been received when the chart was compiled. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unkown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	2	7%							2	7%						
Piping																
Dispenser	6	20%					6	20%								
STP																
Delivery Problem																
Other	22	73%					2	7%					1	3%	19	63%
Totals	30	100%					8	27%	2	7%			1	3%	19	63%

= number, % = percent of total number of releases

Note: Release, source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural Resources.