## **Iowa Department of Natural Resources**

# 2023 Summary Information Underground Storage Tanks (USTs)

#### **General Information**

Public Record Posted Date: 10/9/2023

Total Number Of Active UST Facilities: 2429

Total Number Of Active USTs: 6469

Total Number Of Active UST Compartments: 7824

### **Summary Information For On-Site Inspections**

Number Of UST Facilities Inspected: 1073

Inspection Period Dates: <u>10/1/2022</u> To: <u>9/30/2023</u>

Percent Compliance (Technical Compliance Rate Measure): 20%

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2023. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

## **Summary Information For Releases**

Number Of Confirmed UST Releases: 33

Release Reporting Period Dates: 10/1/2022 To: 9/30/2023

	Cause															
Source			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	2	6%							2	6%						İ
Piping																
Dispenser	14	42%					14	42%								
STP																
Delivery Problem																
Other	17	52%					5	15%							12	36%
Totals	33	100%					19	58%	2	6%					12	36%

# = number, % = percent of total number of releases

Note: Release, source, and cause information is based on releases from underground storage tanks regulated by the lowa Department of Natural Resources.

Questions about the general information, on-site inspections, and confirmed releases may be addressed to the lowa DNR UST Section at 515.725.8450. Site specific information also can be reviewed on the Storage Tanks Database Web Application at https://programs.iowadnr.gov/tanks/pages/advanced.aspx.