

**Iowa Department of Natural Resources  
2023 Summary Information Underground Storage Tanks (USTs)**

**General Information**

Public Record Posted Date: 10/9/2023

Total Number of Active UST Facilities: 2429  
 Total Number of Active USTs: 6469  
 Total Number Of Active UST Compartments: 7824

**Summary Information for On-Site Inspections**

Number of UST Facilities Inspected: 1073  
 Inspection Period Dates: 10/1/2022 To: 9/30/2023  
 Percent Compliance (Technical Compliance Rate Measure): 20%

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2023. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

**Summary Information for Releases**

Number of Confirmed UST Releases: 33  
 Release Reporting Period Dates: 10/1/2022 To: 9/30/2023

| Source           |           |             | Cause |   |          |   |                  |            |           |           |                 |   |       |   |           |            |
|------------------|-----------|-------------|-------|---|----------|---|------------------|------------|-----------|-----------|-----------------|---|-------|---|-----------|------------|
|                  |           |             | Spill |   | Overfill |   | Phys/Mech Damage |            | Corrosion |           | Install Problem |   | Other |   | Unknown   |            |
|                  | #         | %           | #     | % | #        | % | #                | %          | #         | %         | #               | % | #     | % | #         | %          |
| Tank             | 2         | 6%          |       |   |          |   |                  |            | 2         | 6%        |                 |   |       |   |           |            |
| Piping           |           |             |       |   |          |   |                  |            |           |           |                 |   |       |   |           |            |
| Dispenser        | 14        | 42%         |       |   |          |   | 14               | 42%        |           |           |                 |   |       |   |           |            |
| STP              |           |             |       |   |          |   |                  |            |           |           |                 |   |       |   |           |            |
| Delivery Problem |           |             |       |   |          |   |                  |            |           |           |                 |   |       |   |           |            |
| Other            | 17        | 52%         |       |   |          |   | 5                | 15%        |           |           |                 |   |       |   | 12        | 36%        |
| <b>Totals</b>    | <b>33</b> | <b>100%</b> |       |   |          |   | <b>19</b>        | <b>58%</b> | <b>2</b>  | <b>6%</b> |                 |   |       |   | <b>12</b> | <b>36%</b> |

# = number, % = percent of total number of releases

Note: Release, source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural Resources.

Questions about the general information, on-site inspections, and confirmed releases may be addressed to the Iowa DNR UST Section at 515-725-8450. Site specific information also can be reviewed on the Storage Tanks Database Web Application at <https://programs.iowadnr.gov/tanks/pages/advanced.aspx>.